



Specifications	LX 1330A	LX 101
Display	Large 48*31.8mm LCD display	3 1/2 digit 18mm (0.7") LCD
Measuring range	1~100,000 Lux	1 to 50,000 LUX 3 Ranges
3 Measuring Ranges	0-2000/ 2000-19990/ 20000-100000	0-2000/ 2000-19990/ 20000-50000
Accuracy (23°C ±5°C)	≤4%rgd±0.5%f.s	±5%2d
Resolution	0-2000 1Lux/ 2000-19990 10Lux 20000-100000 100Lux	0-2000 1Lux/ 2000-19990 10Lux 20000-50000 100Lux
Response Time	1 second	1 second
Data Hold	√	√
Low Power Indication	√	√
Over Level Indication	√	√
Repeatability	±2%	±2%
Operating Temperature & Humidity	0°C to 50°C (32°F - 122°F) less than 80%R.H.	0°C to 50°C (32°F - 122°F) less than 80%R.H.
Sampling Frequency	1.5 times Second	0.4 seconds
Light Sensor	Built in Rotating Head Movable Clockwise 80° anti clockwise 180° easy to measure	Separate Light Sensor
Power	9v Battery (006 P 9V)	9V Battery (006 P 9V)
Size & Weight	166.2*64.0*30.5mm 116g.	118mmx70mmx29mm 200g.
Accessories Included	Hard Carrying Case and Instruction manual	Carry Case, Light Sensor and Instruction Manual